

Prices valid from 01.01.2019 Service and Upgrade Pentacon Six/Exakta 66

Top (AA-F): Service packages – fixed prices based on an hourly rate
Below: Prices of common service and upgrade package combinations
Prices incl. VAT: German VAT applies for EU citizens only

CLA= Cleaning, Lubricating, Adjusting; **FAC**= baierfoto Film Advance Control unit; **TSR**= baierfoto Two Step Release

	Hours of Work	Hourly Rate	Total before VAT	incl. VAT	Additional charges for Exakta 66	
Red = before VAT Blue = incl. VAT @ 19 per cent						
AA: Checks: shutter cloth, film advance system, mirror, flange focal distance, light seals, glass of focusing field lens, shutter speeds (applies only if no other work order is given)	0,25	35,00 €	8,75 €	10,41 €		
A: Removing dials, levers and top cover, Examining film advance system for mechanical failures	0,5	35,00 €	17,50 €	20,83 €		
B: Disassembling camera, cleaning, lubricating, reassembling of inner unit incl. fix of little malfunctions, replacement of straps on shutter curtain 2	2,5	35,00 €	87,50 €	104,13 €		
C: mounting inner unit into housing, adjust film pressure plate, flange focal distance, stop down lever, frame counter	1,5	35,00 €	52,50 €	62,48 €	20,00 €	23,80 €
D: Adjusting shutter speeds	0,75	35,00 €	26,25 €	31,24 €		
E: Adjusting position of screen and focus including readjustment of stop down lever	1	35,00 €	35,00 €	41,65 €		
F: Mounting top cover, dials and levers, adjusting stop cam of advance lever, final control of shutter speeds, film advance, frame counter and flash synch.	1	35,00 €	35,00 €	41,65 €		
CLA (sum of A to F)			250,00 €	300,00 €	20,00 €	23,80 €
FAC			100,00 €	119,00 €		
TSA w/o CLA (not recommended)			210,00 €	250,00 €	20,00 €	23,80 €
CLA+FAC			330,00 €	390,00 €	20,00 €	23,80 €
CLA+TSR			350,00 €	417,00 €	30,00 €	35,70 €
CLA+FAC+TSR			425,00 €	500,00 €	25,00 €	29,75 €
Shutter speeds records and diagrams (PDF and/or printout)			4,20 €	5,00 €		

Issue: Shutter straps tearing

With age, the shutter straps often lose their tensile strength and are unable to withstand the sudden braking force they are subjected to at the end of the shutter curtain movement. Cleaning and lubricating increases the peak load of the shutter movement as the 'natural' brake effect of old grease has been eliminated. As a result, it is not uncommon for the straps of the second curtain to tear during adjusting after cleaning and lubricating.

Therefore, from now on the two straps of curtain 2 will be replaced in any case – as part of the CLA without additional charge.